

## **GROUP 42**

### **BODY**

#### **GENERAL**

##### **OUTLINE OF CHANGES**

To correspond to the abolition of manual operation in the event of a sunroof problem, a function which releases the clamping prevention mechanism and allows operation to continue until fully closed (for a distance of 30 mm) has been provided for cases when reversing occurs repeatedly for 5 times or more due to deformation (clamping prevention mechanism is operating). The sunroof wrench has also been abolished.